

## Parallel Port (25-pin):

Pin	Signal	Pin	Signal
1	-Strobe	14	-Autofeed XT
2	D0	15	-Error
3	D1	16	-Init
4	D2	17	-Slct in
5	D3	18	Ground
6	D4	19	Ground
7	D5	20	Ground
8	D6	21	Ground
9	D7	22	Ground
10	-ACK	23	Ground
11	Busy	24	Ground
12	PE	25	Ground
13	Slct		

## Serial Port (9-pin):

Pin	Signal
1	Carrier Detect
2	Receive Data
3	Transmit Data
4	Data terminal ready
5	Signal ground
6	Data set ready
7	Request to send
8	Clear to send
9	Ring indicate

(jej-05/10/94)