

## SCO XENIX 2.2.4 (25-5200) OR 2.3.2 GT (25-5203) PRINTER PORTS

On the 4016DX (250-5001), 4020LX (250-5120), 4025LX (250-5125), 4033LX (250-5130), and 5000MC (250-6000), the printer ports are defined differently with SCO Xenix release 2.2.4 (250-5200) or 2.3.2 GT (250-5203). The chart below shows the correct port number for xenix and the port number under the CMOS setup for the on board printer port.

| CMOS Printer Option | Xenix Printer Port |
|---------------------|--------------------|
| Printer-1           | lp1                |
| Printer-2           | lp0                |
| Printer-3           | lp2                |

All other computers that do not control the on board printer port by the CMOS setup, will be as follows:

| Printer Port Number | Xenix Printer Port |
|---------------------|--------------------|
| lpt-1               | lp0                |
| lpt-2               | lp1                |
| lpt-3               | lp2                |