

Parallel Port

Pin	Assignments	Pin	Assignments
1	Strobe *	14	AUTOFEED *
2	Data Bit 0	15	ERROR *
3	Data Bit 1	16	INITIALIZE *
4	Data Bit 2	17	SELECT IN *
5	Data Bit 3	18	Ground
6	Data Bit 4	19	Ground
7	Data Bit 5	20	Ground
8	Data Bit 6	21	Ground
9	Data Bit 7	22	Ground
10	ACKNOWLEDGE *	23	Ground
11	BUSY	24	Ground
12	PAPER END	25	Ground
13	SELECT		

* Denotes low true logic.

Serial Port

Pin	Assignments
1	Carrier Detect
2	Receive Data
3	Transmit Data
4	Data Terminal Ready
5	Signal Ground
6	Data Set Ready
7	Request to Send
8	Clear to Send
9	Ring Indicator

(smm 08/03/93)

□